

# Lloyds Register Approved Service Supplier

<b>Supplier</b>	<b>Beyond Marine Safety Pte Ltd</b>
<b>Address</b>	9 Tuas South Ave 10, T99 Building #04-09/10, Singapore, 637014, Singapore
<b>Contact Details</b>	Email: sales@beyondmarinesafety.com
<b>Contact Number</b>	Tel: +65 8138 7818

The above company having been assessed hereby receives approval in accordance with the requirements of Lloyd's Register Procedures for Approval of Service Suppliers as Supplier from the address(es) listed above for the provision of

**Maintenance, thorough Examination, Operational Testing, Overhaul and Repair of Lifeboats and Rescue Boats, Launching Appliances and Release Gear**

This Service Supplier has been approved to service the equipment in accordance with IMO Resolution MSC.402(96)/Corr.1.

Service engineers are to be provided with a valid Certificate, issued by this Approved Service Supplier, which defines their level of qualification and the scope of the certification (i.e. makes and types of equipment and specifically state which activities (e.g. annual thorough examination and operational tests; 5-year thorough examination, overhaul; overload operational tests; repairs) are covered by the certification). This Certificate should be made available when requested.

**Sam Yap**

Senior Surveyor - Marine to Lloyd's Register  
Singapore Pte Ltd  
A member of the Lloyd's Register group

---

## Lloyds Register Approved Service Supplier

This approval is conditional upon the Supplier maintaining the documented scheme as audited by any member of the Lloyd's Register Group and hereby approved; and notifying Lloyd's Register in writing of any change to that scheme including any change in personnel, equipment or procedures. This certificate is issued to the Supplier and, subject to the Supplier complying with the necessary conditions, is valid to the date referred to above.

1 Fusionopolis Place, #09-11 Galaxis, 138522,  
Singapore

---

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.



## APPENDIX A

Office: **Singapore**Date: **19 August 2020**

This Certificate is issued to BEYOND MARINE SAFETY

The service supplier has been approved to service the following equipment in accordance with MSC.402(96).

No.	Maker	Type
1	Qingdao Beihai Shipbuilding Heavy Industry Co., Ltd	<p><b>Totally Enclosed Lifeboat:</b> BH-5/BH-5A/BH-5S/BH-5SA/BH-E500/BH-E585/BH-6/BH-6A/BH-6S/BH-E670/BH-7A/BH-7B/BH-8</p> <p><b>Free Fall Lifeboat:</b> BH-F6.0/BH-F7.0A/BH-F7.8/BH-F8.1/BH-F5.8/BH-F6.8/BH-F660/BH-F670/BH-F750</p> <p><b>Rescue Boat:</b> BH-R4/BH-R4S/BH-R4SA/BH-R5S/BH-HR6/BH-HR7</p> <p><b>Gravity Pivot Davit:</b> BD-PV50/BD-PV60/BD-PV60S/BD-PV85/BD-PV125</p> <p><b>Free Fall Davit:</b> BD-FF55/BD-FF55A/BD-FF55R/BD-FF80/BD-FF80A/BD-FF80R/BD-FF80B/BD-FF66/BD-FF67/BD-FF85</p> <p><b>Single Arm Davit:</b> BD-SA14/BD-SA14A/BD-SA14B/BD-SA21/BD-SA21A/BD-SA23/BD-SA30/BD-SA30A/BD-SA33/BD-SH23</p> <p><b>Winch:</b> BW-H(L/R)31 / BW-H(L/R)50 / BW-H(L/R)63 / BW-H(L/R)75 / BW-L(L/R)75 / BW-L(L/R)125 / BW-SC14 / BW-SC21</p> <p><b>Release Mechanism - Gravity Lifeboat:</b> BG-3/BG-3L/BG-7/BH-HOOK3/BH-HOOK5/FS5/FS7</p> <p><b>Release Mechanism - Free Fall Lifeboat:</b> BG-3.5F/BG-4F/BG-4.5F/BG-4.5FL/BG-5F/BG-6F</p> <p><b>Release Mechanism - Rescue Boat:</b> BG-2R/15KNXS/25KNXS/35KNXS</p>
2	Wuxi Dongwu Marine Equipment Co., Ltd	<p><b>Gravity Luffing Arm Davit:</b> 18KN/25KN/40KN/50KN/60KN/60KN(60L)/85KN/110KN/T2.5/SK50</p> <p><b>Gravity Sliding Track Davit:</b> 25KN/30KN</p> <p><b>Free-Fall Lifeboat Launching Appliance:</b> F55/F70/NPT100F</p> <p><b>Rescue Boat/ Liferrafts Launching Appliances:</b> 21KN(manual) / 21KN(Electrical) / 21KN (Electrical / Hydraulic) / DWC210 / 25KN (Electrical / Hydraulic) / 35KN (Electrical / Hydraulic)</p> <p><b>Rescue Boat Launching Appliances:</b> A30/ H35</p>

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

		<p><b>Lifeboat Winch:</b> DS*ZY25/DS*ZY40/D50S/DS*ZY63/D63S/80KN (Life)</p> <p><b>Life/ Rescue Boat Winch:</b> DZY/Z21/DZ*ZY25/DZ*ZY40/D50Z/DZ*ZY63/D63Z/80KN(rescue)</p>
3	Zhejiang Hengxin Ship Equipments Co., Ltd	<p><b>Lifeboat Series:</b> BCC/BCF/BCFC/BCFF</p> <p><b>Rescue Boat Series:</b> GJ/FRH/RH</p> <p><b>Release Mechanism Series:</b> HK</p> <p><b>Davit Series:</b> FH /SA/HDC/LFR/LR/HE/PD/SRH/LB/KN</p>
4	Zhenjiang DH Marine Equipment Co., Ltd	<b>Davit:</b> HSD23/HSD15/PR30/PRH35/MSD23/MSD33/LE120/LE90
5	Vanguard Pte Ltd	<p><b>Lifeboat:</b> VG4.9/VG5.9/VG5.7/VG7.5/VG8.5/VG9.6/VG10.5/VG11.95/VG12.05</p> <p><b>Rescue/ Fast Rescue Craft:</b> VG4.0/VG4.5/ VG6</p> <p><b>Hooks:</b> QRH35/Csafe 3.5/Csafe 5/ Csafe 5 Mk.II/Csafe 8.5/Csafe 8.5 Mk.II/Csafe 10/Csafe 10 Mk.II/Csafe 14</p>
6	CSSC Luzhou Zhenjiang Marine Auxiliary Machinery Co., Ltd	<p><b>Totally Enclosed Lifeboat:</b> YH5.0/YH6.5/YH8.5/YH10.3/YH9.5/YH12/YH12.5/YH9.9</p> <p><b>Free Fall Lifeboat:</b> YH5.9/YH6.7/YH7.5/YH8.5</p> <p><b>Fast Rescue Boat:</b> YH6.0/YH6.5</p> <p><b>Rescue Boat:</b> YH4.5</p> <p><b>Gravity Davit:</b> LE55/LE65/LE85/ LE100/LE138/LE170/HE65/HE85/HE100</p> <p><b>Launching Appliance Davit:</b> FH55/FH70/FH75/FH85/FH100</p> <p><b>Single Arm Davit and Crane:</b> SAF14/SAFC21/SAFC25/SA32/HDCL2-6.5/HDCL3-6/HDCL3-10</p> <p><b>Off-shore Davit:</b> PL65/PL85/PL100/PL110/PL138</p> <p><b>Fast Rescue Boat Davit:</b> LFR30/LFR35/LFRH30/DH30</p>
7	Sheyang Saifute Marine Auxiliary Machinery Plant Jiangsu	<p><b>Gravity Luffing Arm Davit:</b> 14KN/25KN/50KN/60KN/90KN/100KN/120KN</p> <p><b>Gravity Sliding Track Davit:</b> 15KN/40KN</p> <p><b>Cross Deck Gravity Sliding Track Davit:</b> 30KN/110KN</p> <p><b>Platform Davit:</b> 48KN/110KN</p> <p><b>Free Fall Lifeboat Launching Appliance:</b> 55KN/70KN</p> <p><b>Single Arm Rescue Davit:</b> 10KN/14KN/SFTSA10DS</p> <p><b>Single Arm Rescue Boat/ Raft Launching Appliances:</b> 21KN/25KN/40KN</p>

		<p><b>Lift-Raft Launching Appliance:</b> 21KN/25KN</p> <p><b>Single Arm Rescue Boat/ Raft Launching Appliances &amp; Provisions Crane:</b> 21KN</p> <p><b>Hydraulic Slewing Boat-Raft Davit:</b> SFT-14KN/FCD3T*10M/25KN*10M</p> <p><b>Fast Rescue Boat Davit:</b> SFT-AFR25</p> <p><b>Ele. Rescue Boat Winch:</b> 25KN/40KN/D50Z/63KN/E100R/D100Z</p> <p><b>Ele. Lifeboat Winch:</b> 14KN/25KN/40KN/ D50S/ 63KN/ E70L/D100S/ E100L</p>
8	Wuxi Hai Hong Boat Making Co., Ltd.	<p><b>Totally enclosed life / rescue boat series:</b> HH70C / HH70T; (QFP7.0/QFN7.0); HH85CS / HH85TS (QFP8.5/QFN8.5); HH65CS / HH65TS (QFP6.5/QFN6.5); HH75CS / HH75TS (QFP7.5/QFN7.5); HH80CS / HH80TS (QFP8.0/QFN8.0); HH65C / HH65T; (QFP(H)6.5/QFN(H)6.5); HH50C / HH50T; HH53C / HH53T; (QFP(H)5.3); HH75C (QFP(H)7.5); HH85C / HH85T; HH57C / HH57T</p> <p><b>Freefall Lifeboat Series:</b> HH59FC / HH59FF; HH76FC / HH76FF</p> <p><b>Rescue Boat Series:</b> GJ4.5B / GJ4.5B1</p> <p><b>High Speed Rescue Boat Series:</b> GJ618A / GJ618B</p> <p><b>Release Gear Series:</b> HH76 /HH43/ HH30/ HH20</p>

The following personnel is approved to carry out the service for the equipment shown in above list:

1) MR. TAN WUAN PING – For all makers and types in above list;

This Appendix shall be attached to the Service Supplier Approval Certificate LR2011461AS and no signature required as it is issued electronically.

T.S. Yap

Surveyor to Lloyd's Register Singapore Pte. Ltd.

a member of the Lloyd's Register group.